



Central Oregon Coast Fire and Rescue District

P.O. Box 505, 145 East Alsea Hwy
Waldport, Oregon 97394
Phone (541) 563-3121 Fax (541) 563-3190



THIS IS NOT A PERMIT TO BURN

HOME INCINERATOR TIPS

BURN IN A SAFE INCINERATOR:

SHOWN BELOW IS A BARREL TYPE INCINERATOR, ILLUSTRATING MINIMUM FIRE SAFETY REQUIREMENTS. FOR OTHER TYPES OF INCINERATORS, CONTACT YOUR LOCAL FIRE DEPARTMENT.

WHEN YOUR INCINERATOR MEETS THESE MINIMUM REQUIREMENTS, CONTACT YOUR LOCAL FIRE DEPARTMENT

HOME INCINERATOR TIPS

MINIMUM REQUIREMENTS FOR YOUR SAFETY AND PROTECTION

1. THIS IS NOT A PERMIT TO BURN:
WHEN YOUR INCINERATOR MEETS THESE MINIMUM REQUIREMENTS CONTACT YOUR LOCAL FOREST OFFICER FOR A PERMIT TO USE YOUR INCINERATOR.
2. BURN IN A SAFE INCINERATOR : *
*(SHOWN BELOW IS A BARREL TYPE INCINERATOR, ILLUSTRATING MINIMUM FIRE SAFETY REQUIREMENTS. FOR OTHER TYPES OF INCINERATORS CONTACT YOUR LOCAL FOREST OFFICER.)

HEAVY SCREEN MESH


NOT LESS THAN 14 GAUGE WIRE WITH HOLES NOT LARGER THAN 3/8".

METAL BARREL

IN GOOD CONDITION.

GROUND CLEARED

AND MAINTAINED AT LEAST 10 FEET AROUND INCINERATOR OF ALL MATERIAL THAT COULD CAUSE YOUR FIRE TO ESCAPE. MORE CLEARANCE MAY BE REQUIRED.



IF YOU DON'T PREVENT FIRES ----- WHO WILL ?

"Dedicated to caring for South Lincoln Communities"

try us out at: www.centralcoastfire.net